

# Danni alla vasca Pam 1 - 2019

09/08/2019

---

## **Danni alla vasca Pam 2 dell'Obbitu Village**

the floor of dam liner of pan 2 has several holes which we are trying to close with repairs. the holes were due to cut from recent de-silting and and some damage from bottom of the floor.the biggest damage is from the inlet channel where the dam liner detached from the wall allowing water to flow into the earth wall of the pan causing erosion and moving soil and the layer of the dam liner. . may be the pictures attached can explain batter.

the option we have is to add another dam liner on top . in short term we shall repair the holes and for the wall remove the overlapping and reposition to stop water flowing between the earth wall and the dam liner.

---

il pavimento del rivestimento della diga della vasca 2 presenta diversi fori che stiamo cercando di chiudere con le riparazioni. i fori erano dovuti al recente disinserimento e ad alcuni danni dal fondo del pavimento. il danno maggiore è dal canale di ingresso in cui il rivestimento della diga si staccava dalla parete permettendo all'acqua di fluire nella parete di terra della vasca causando l'erosione e movimento del suolo e lo strato del rivestimento della diga. l'opzione che abbiamo è quella di aggiungere un altro rivestimento della diga in cima. a breve termine ripareremo i fori e per il muro rimuoveremo la sovrapposizione e riposizioneremo per impedire all'acqua di fluire tra il muro di terra e il rivestimento della diga.